



| Service Name | Service Fee | Service Description |
|----------------------------------------------------------|------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| *Pac-Lite Thread Repair | \$40 + \$20/threaded tap | Repairing Front/Rear Sight Taps, Scope Base Taps |
| *Pac-Lite End Cap / Compensator Pinning | \$60 | Permanently attaching End Cap / Compensator. TacSol will only affix TacSol Compensator / End Cap. |
| Non-Serialized Barrel End Cap / Compensator Pinning | \$50 | Permanently attaching End Cap / Compensator. TacSol will only affix TacSol Compensator / End Cap. |
| Non-Serialized Thread Repair (Rifle Barrels, Trail-Lite) | \$25 + \$20/threaded tap | Repairing Front/Rear Sight Taps. If muzzle threads are damaged, barrels will not be cut/rethreaded |
| Barrel or Conversion Cycling or Accuracy Diagnosis | \$25 + Hourly + Ammunition + Parts | Identifying and correcting failures to feed, fire, extract, eject. Concerns about accuracy. Rifle barrels guaranteed at 1" at 50 yards. Includes cycling test. |
| *Rifle Cycling or Accuracy Diagnosis | \$40 + Hourly + Ammunition + Parts | Identifying and correcting failures to feed, fire, extract, eject. Concerns about accuracy. Rifle barrels guaranteed at 1" at 50 yards. Includes cycling test. |
| *Pac-Lite / Trail-Lite Installation | \$75 + Hourly | Installing Pac-Lite onto Ruger® Mark I – III Frame. Installing Trail-Lite onto Browning Buckmark Frame. Includes cycling test. |
| X-Ring Barrel Squib Replacement | \$150 | Replacing barrel that has encountered squib rupture due to ammunition. |
| *Owyhee Barrel Squib Replacement | \$200 | Replacing Owyhee TD barrel that has encountered squib rupture due to ammunition. The entire rifle must be retrieved to properly fit barrel. Includes cycling test. |
| X-Ring Barrel Installation | \$75 | Installing customer-purchased barrel into customer's receiver. Includes cycling test. |

| | | |
|-----------------------------------------|----------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Suppressor Baffle / End Cap Replacement | \$40 + Parts | Replacing baffles and end cap because of baffle / EC strikes. Applies to Aeris, Ascent22 and Axiom suppressors. Entire suppressor must be shipped. Lost / Missing baffles / EC shall not be replaced per ATF rules. |
| Firearm Cleaning | \$75 | Clean and function test customer's TacSol firearm. TacSol will only provide this service for complete X-Ring/ Owyhee rifles and Pac-Lite TSS, X-Ring TSS, and Axiom, Ascent22 and Aeris suppressors. Service includes cleaning and cycling test. |
| Parts | \$TBD | TacSol will cover the cost of most small parts, such as springs, pins, screws and similar. Replacement of major components, such as bolt assemblies, barrels, trigger group components, rear sight assemblies, baffles, end caps, and similar will be at customer expense. Subject to TacSol discretion. |
| Ammunition | \$5 / 50rds (CCI Mini Mag/ Blazer) \$15 / 50rds (Lapua, Eley, SK) | All cycling tests will be conducted with CCI Mini Mag or Blazer ammunition. Lapua, Eley and SK available upon request at additional fee. |
| Unapproved RA | \$25 | This fee will be incurred if items arrive without prior TacSol contact and authorization. |

Tech Support Fee Schedule and RA Basics

-General Labor Rate is \$60/hr. and will be counted in 6-minute (1/10th hr.) increments.

Please allow up to 10 business days from the day of receipt for RA completion.

-Listed base fee includes return shipping. For RAs with firearms, base fee includes shipping to TacSol and shipping from TacSol as we must provide the label.

-All Repair Authorizations subject to TacSol discretion. Any item found to be beyond repair will be returned without action at the customer's expense if arrangements are not made to purchase replacement. Any TacSol product with components found to have been modified from its original condition, where that modification affects the functionality of the item, will be replaced at the owner's expense.

-All service payments will be collected at the end of the RA, prior to return shipment. Items will not be returned until service payment has been received in full.

-Serialized portion of suppressors may not be replaced under any circumstances without incurring new NFA Tax Stamp approval process. If suppressor is damaged beyond repair, TacSol may issue a discount toward a replacement, at TacSol's discretion.

-When shipping firearms and firearms components, it is highly encouraged to ship your items in a new-condition, sturdy, and non-descript box. Ensure the contents are properly packaged with padding material and ensure all flaps are securely taped. **TacSol will not be liable for any damages that occur to the firearm or any attached accessories during shipment.**